

Release Notes

XRS2i & SRS2i v1.4.12.17

19 Aug 2025

New firmware for the SRS2i and XRS2i

DATAMARS
Livestock™

Release date: 03/Sept/2025
Version Number: 1.4.12.17

This firmware addresses a bug that was in the 1.4.12.0 release. Older I series stick readers that were once on firmware 1.4.11.0 that then were updated to 1.4.12.0, had the screen go white. This affected a small number of customers.

This bug.
is now fixed in the 1.4.12.17 version, stick readers that have this issue should be able to connect to Datalink PC and be updated to get this fix.
For other customers, there is no change in functionality compared to 1.4.12.0
This is only a main firmware update. The Bluetooth firmware can remain on v1.1.4.



Previous Releases

- Main Firmware v1.4.12.0, BT 1.1.4
 - Added support for the Bluetooth session printers connection with thermal printers (eg the Netum Mini Pos Printer)
 - Fixed the unexpected “low battery” shutdown despite sufficient charge
 - Improved the Dam EID display
- Main Firmware v1.4.11.34, BT 1.1.4
 - Added support for Bluetooth auto reconnect when in HID mode
 - Added support on the XRS2i for the Zebra Barcode Printers (ZQ500 series, and QNL320)
 - Added support for receiving weights from the JR/ID/XR5000
 - Improved Bluetooth connections with smart phones/tablets/PCs
 - Fixed the lock-up issue when reading in continuous mode
- Main Firmware v1.4.11.16, BT 1.1.2
 - Added feature to input barcode into VID
 - Added barcode scanner support
 - Fixed auto power off issue
 - Fixed HID extra digits issue